

Manual Supplement

Manual Title: 5790A Service Manual
Part Number: 893292
Print Date: January 1992
Revision/Date: 5, 1/07

Supplement Issue: 1
Issue Date: 10/18
Page Count: 1

This supplement contains information necessary to ensure the accuracy of the above manual.

FLUKE®

Calibration

Change #1, 603

On page 3-65, under **3-33 WIDEBAND 1-kHz GAIN VERIFICATION, 22 mV RANGE**, replace Step 1 with:

1. Use the attenuators specified in Table 3-9 to connect the equipment as shown in Figure 3-19. **DO NOT CONNECT** the HP 3458A input to the Type "N" tee at this time. Set the HP 3458A to ACV, "SETACV SYNC," "RES .001."